




NOTE: IF USING GALVANIZED PIPE, WELL VENTILATED AREA TO PREVENT OXIDE POISONING.

The diagram shows a cross-section of a pipe with a flange on the left and a coupling on the right. A vertical line extends from the top of the pipe, and a horizontal line extends from the right side of the pipe. A small circle is located near the bottom of the pipe, and a small arrow points to the right. The entire diagram is enclosed in a rectangular box.



PERSPECTIVE

NO SCALE

STRAP STEEL CUTTING DIAGRAM SCALE: $\frac{1}{2}'' = 1'$ 


BLACK IRON PIPE CUTTING DIAGRAM

SCALE: $\frac{1}{8}'' = 1'$



HINGE DETAILS

SCALE: $\frac{1}{2}'' = 1'$



COOPERATIVE EXTENSION SERVICE
AGRICULTURE AND HOME ECONOMICS
Agricultural Extension Service
University of Tennessee Institute of Agriculture
Agricultural Experiment Station

UNITED STATES DEPARTMENT OF AGRICULTURE AND
FOREST SERVICE

ASSEMBLY DRAWINGS

SCALE: $\frac{3}{16}'' = 1''$

12" LOG LIFTER

W VA'86	6379
---------	------

SHEET | OF |