## Studio N

Start up ↓		Shut Down 🥠	
HDD	10 sec Rev Up	Files	– Save all
MIDI Interfaces Ω	Turn On	Close Programs	Close All Programs
Monitor Station	Lower Master Vol	Exit Pro-Tools	File - Exit
M- Powered I/O	Turn On	Pre Amp	Power Off
Computer	Start up, Log On	<b>Monitor Station</b>	Lower Master Output
Pro - Tools	Find File Associations	Computer	Log Off, Shut Down
Pre Amp	Best after 1 hr	M-Powered I/O	Shut Down
MRS 802	Allow 2 minutes	MRS 802	Turn Off
		MIDI Interfaces Ω	Turn Off
		HDD	Unplug Cables